

General Information

Date & Time: 29, Jul, 2025 13:21

Make	Suzuki	Model	Carry
YOM	2024	Odo Meter Reading	8,752
Registration No.	DBP2439	Chassis No.	MHYDC61T4SJ210386
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Pickup
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.3	123	107	110
2	Boot Lid	121.0	119	122	122
3	Roof	95.0	103	107	85/85
4	Left Front Fender	117.6	110	123	120
5	Left Front Door	103.6	100	109	102
6	Center Panel Left	99.1	100	103	94
7	Left Rear Door				
8	Left Back Panel	228.6	222	255	209
9	Right Front Fender	122.0	115	121	130
10	Right Front Door	96.1	101	100	87
11	Center Panel Right	94.0	101	95	86
12	Right Rear Door				
13	Right Back Panel	247.0	185	344	212

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Loose, Deformed - Medium / Ceiling - Crinkle - Large / (R) Front Floor Mat - Worked - Small / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Medium / (R) Front Trim - Cut, Crack - Small	Remarks (R) Side Gate - Repair mark - Yes / (L) Side Gate - Repair mark - Yes / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Side Gate - Scratch - Small / Rear Gate - Scratch - Small / Cargo Bed Floor - Scratch - Medium / (L) Side Gate - Scratch - Small / (L) Front Door, Molding - Scratch - Medium / (L) Center Panel - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Front Panel - Dent - Medium / Roof - Scratch & Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
no warranty booklet, no jack and tools, with spare tire, with LTO plate