


General Information

Date & Time: 29, Jul, 2025 14:41

Make	Toyota	Model	Rush
YOM	2023	Odo Meter Reading	69,611
Registration No.	EAG2127	Chassis No.	MHKE8FE2PNK005040
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Wagon
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.6	108	103	127
2	Boot Lid	144.6	145	131	158
3	Roof	104.5	87	82	144/105
4	Left Front Fender	101.3	98	96	110
5	Left Front Door	101.3	96	96	112
6	Center Panel Left				
7	Left Rear Door	103.0	111	97	101
8	Left Back Panel	146.6	157	132	151
9	Right Front Fender	96.7	100	97	93
10	Right Front Door	101.8	106	100	100
11	Center Panel Right				
12	Right Rear Door	99.2	96	96	106
13	Right Back Panel	95.2	87	97	102

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat Head Rest - Missing - Yes / Overall Interior - Smell - Yes / Rear Seat - Grime - Small	Remarks (R) Rear Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

With LTO plate and Sparetire and Warranty booklet. Jack and Incomplete Tools. scratch headlight and tail light.