


General Information

Date & Time: 22, Jul, 2025 10:39

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	30,597
Registration No.	NFR1388	Chassis No.	PA1B18F30R4247647
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.3	125	105	110
2	Boot Lid	106.0	105	106	107
3	Roof	104.7	103	105	102/109
4	Left Front Fender	106.2	100	119	100
5	Left Front Door	96.2	97	91	101
6	Center Panel Left				
7	Left Rear Door	103.5	110	103	98
8	Left Back Panel	105.4	115	104	97
9	Right Front Fender	100.3	103	99	99
10	Right Front Door	101.0	103	98	102
11	Center Panel Right				
12	Right Rear Door	106.8	96	104	120
13	Right Back Panel	98.9	101	100	96

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Worn - Yes / Rear Seat - Worn - Yes / (R) Rear Trim - Cut, Crack - Minimal / (R) Front Trim - Grime - Minimal / (L) Front Floor Mat - Cut, Crack - Small / (L) Front Floor Mat - Worked - Large / (L) Front Trim - Grime - Minimal / Ceiling - Grime - Minimal	Remarks (R) Front Fender, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on tail light