


General Information

Date & Time: 22, Jul, 2025 15:24

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	9,701
Registration No.	VAB9597	Chassis No.	PA1B18F3XR4247154
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	121	101	119
2	Boot Lid	110.6	109	100	123
3	Roof	101.9	103	106	94/105
4	Left Front Fender	105.1	114	94	107
5	Left Front Door	107.0	113	108	100
6	Center Panel Left				
7	Left Rear Door	112.0	112	105	119
8	Left Back Panel	114.3	137	106	100
9	Right Front Fender	103.6	107	102	102
10	Right Front Door	106.3	111	100	108
11	Center Panel Right				
12	Right Rear Door	110.0	112	105	113
13	Right Back Panel	113.3	109	113	118

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Trunk Room - Worn, Scratch, Cut, Crack - Small / Mat Other - Missing - Yes / Rear Seat - Grime - Small / (L) Front Floor Mat - Worked - Small / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Minimal	Remarks (R) Front Wheel, Cover - Scratch, Corrosion - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (R) Rear Wheel, Cover - Scratch, Corrosion - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate, no warranty booklet, with jack, incomplete tools, with spare tire, tow hook cover missing