

General Information

Date & Time: 21, Jul, 2025 17:41

Make	Hino	Model	315
YOM	2024	Odo Meter Reading	6,450
Registration No.	NKG9462	Chassis No.	JHHAGP6ERK004829
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	MPV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	92.4	91	92	94
2	Boot Lid	153.3	173	139	148
3	Roof	83.5	92	85	94/63
4	Left Front Fender	90.8	90	91	92
5	Left Front Door	90.1	89	84	98
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	148.3	155	135	155
9	Right Front Fender	89.1	90	90	87
10	Right Front Door	64.7	70	66	58
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	214.3	320	126	197

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Medium / (R) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium</p>	<p>Remarks (R) Rear Corner Panel - Repair Traces - Yes / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Side Gate - Scratch - Medium / (R) Side Window - Damaged - Large / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Side Gate - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Mirror - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>Without warranty booklet. With Spare tire,jack and tools. 3 keys. With LTO plate.</p>