

General Information

Date & Time: 24, Jul, 2025 13:15

Make	Toyota	Model	Hilux
YOM	2025	Odo Meter Reading	4,742
Registration No.	BAG8212	Chassis No.	MR0BA3CD2R6617319
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.3	114	127	114
2	Boot Lid	99.2	99	101	98
3	Roof	121.5	114	124	132/116
4	Left Front Fender	111.6	114	110	111
5	Left Front Door	137.3	131	137	144
6	Center Panel Left				
7	Left Rear Door	136.0	137	137	134
8	Left Back Panel	115.3	114	116	116
9	Right Front Fender	112.3	114	108	115
10	Right Front Door	107.3	111	108	103
11	Center Panel Right				
12	Right Rear Door	102.0	94	102	110
13	Right Back Panel	104.6	100	110	104

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : A
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Medium / Mat Other - Grime - Medium / (R) Rear Trim - Grime - Small / (L) Rear Trim - Grime - Minimal / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Grime - Small</p>	<p>Remarks (L) Side Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>G variant mags installed not GRS mags. With warranty booklet and spare tire. Without jack and tools. 2 keys. LTO plate not installed in this unit.</p>