

## General Information

Date & Time: 24, Jul, 2025 13:59

<b>Make</b>	Toyota	<b>Model</b>	Innova
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	7,484
<b>Registration No.</b>	CCG4122	<b>Chassis No.</b>	PA2JA8EM0R0146648
<b>CC</b>	2.8	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Wagon
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.3	101	118	115
2	Boot Lid	90.8	95	86	92
3	Roof	96.1	108	97	88/92
4	Left Front Fender	101.4	104	106	94
5	Left Front Door	106.3	108	109	102
6	Center Panel Left				
7	Left Rear Door	104.3	112	101	100
8	Left Back Panel	109.2	111	99	118
9	Right Front Fender	102.5	96	110	102
10	Right Front Door	99.3	101	103	94
11	Center Panel Right				
12	Right Rear Door	99.6	100	99	100
13	Right Back Panel	107.6	104	100	119

## Overall Evaluation :

A

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>B</b>	<b>Exterior Evaluation :</b>	<b>B</b>
			
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (R) Front Trim - Grime - Small / Mat Other - Grime - Medium / Ceiling - Grime - Small / (R) Rear Trim - Grime - Minimal / (L) Rear Trim - Grime - Minimal / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Worked - Small</p>		<p><b>Remarks</b> (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Roof - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>A</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Defects not found</p>	

## Inspector Notes

With warranty booklet, spare tire, jack, tools, and seat cover. 2 keys. With LTO plate.