

General Information

Date & Time: 24, Jul, 2025 14:36

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	2,802
Registration No.	BAF6054	Chassis No.	PA1B18F3P4214091
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.6	100	107	101
2	Boot Lid	95.9	94	97	97
3	Roof	91.1	92	97	87/88
4	Left Front Fender	89.4	90	89	89
5	Left Front Door	94.7	96	91	98
6	Center Panel Left				
7	Left Rear Door	95.6	103	95	89
8	Left Back Panel	102.7	110	97	101
9	Right Front Fender	91.0	92	89	93
10	Right Front Door	93.0	92	92	95
11	Center Panel Right				
12	Right Rear Door	96.4	90	95	104
13	Right Back Panel	103.1	101	96	112

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Small / Rear Seat - Grime - Small / (L) Front Trim - Grime - Small</p>	<p>Remarks (L) Front Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Large / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>Low battery. With warranty booklet, spare tire, jack and tools. Without seat cover. 2 keys. With LTO plate.</p>