

General Information

Date & Time: 01, Aug, 2025 12:31

Make	Toyota	Model	Vios
YOM	2018	Odo Meter Reading	77,334
Registration No.	DAD4296	Chassis No.	PA1B13F31J4062966
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.3	119	116	105
2	Boot Lid	102.6	103	101	104
3	Roof	110.7	109	106	119/109
4	Left Front Fender	105.3	108	104	104
5	Left Front Door	114.0	115	107	120
6	Center Panel Left				
7	Left Rear Door	113.6	107	117	117
8	Left Back Panel	104.6	103	106	105
9	Right Front Fender	113.0	115	116	108
10	Right Front Door	107.3	109	107	106
11	Center Panel Right				
12	Right Rear Door	110.6	116	111	105
13	Right Back Panel	108.0	109	110	105

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Medium / (L) Front Floor Mat - Cut, Crack - Medium / Carpet - Worked - Minimal / Ceiling - Grime - Minimal / Overall Interior - Worn as per age - Yes / (L) Front Seat - Worn - Yes / (R) Rear Trim - Cut, Crack - Small</p>	<p>Remarks (R) Front Fender, Molding - Dent - Medium / (R) Mirror - Scratch - Small / (L) Mirror - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Large / (L) Front Fender, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Medium / Roof - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on tail light, plate and park light issue, fog lamps issue</p>