

General Information

Date & Time: 25, Jul, 2025 10:44

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	1,293
Registration No.	NHU7209	Chassis No.	PA1B18F36R4276716
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.1	115	106	97
2	Boot Lid	104.3	97	111	105
3	Roof	93.6	91	94	93/97
4	Left Front Fender	94.7	103	91	91
5	Left Front Door	97.3	96	93	103
6	Center Panel Left				
7	Left Rear Door	102.5	109	103	96
8	Left Back Panel	104.6	110	104	100
9	Right Front Fender	93.2	89	90	100
10	Right Front Door	99.5	107	95	97
11	Center Panel Right				
12	Right Rear Door	100.1	90	96	115
13	Right Back Panel	100.7	100	95	107

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Medium / Mat Other - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Grime - Medium</p>	<p>Remarks (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>Without warranty booklet and tools. With spare tire,jack,and seat cover. 3 keys. With LTO plate.</p>