

General Information

Date & Time: 25, Jul, 2025 13:07

Make	Toyota	Model	Fortuner
YOM	2019	Odo Meter Reading	66,134
Registration No.	DBA5673	Chassis No.	MHFGB8GS1K0901495
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	Brown		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.0	110	116	113
2	Boot Lid	97.2	90	113	89
3	Roof	114.0	117	116	110/113
4	Left Front Fender	165.0	165	161	169
5	Left Front Door	111.6	121	113	101
6	Center Panel Left				
7	Left Rear Door	97.1	108	96	87
8	Left Back Panel	107.3	110	107	105
9	Right Front Fender	102.2	106	100	101
10	Right Front Door	105.6	107	101	109
11	Center Panel Right				
12	Right Rear Door	100.6	93	97	112
13	Right Back Panel	100.3	100	89	112

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Grime - Small / Ceiling - Grime - Small / Mat Other - Grime - Small / (L) Front Floor Mat - Worked - Small / Sunvisor, Sunglass Holder - Grime - Small / Steering Wheel - Worn, Peel, Crack - Medium</p>	<p>Remarks (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Dent - Small / (R) Front Fender, Molding - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Power Window (each) - Stuck, Gap - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>After market mags and tires. Dead battery. Front and rear right power window issue. driver side hand railing issue. Trunk door cannot open. Sunglass holder issue. without warranty booklet and spare tire. cannot confirm, if with Jack and tools due of trunk door cannot open. 1 key. With LTO plate.</p>