

General Information

Date & Time: 01, Aug, 2025 13:34

Make	Lexus	Model	ES
YOM	2020	Odo Meter Reading	47,994
Registration No.	DBA3162	Chassis No.	JTHBZ1B10L201067
CC	3.5	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.1	95	113	96
2	Boot Lid	152.3	152	160	145
3	Roof	175.5	168	188	168/178
4	Left Front Fender	99.2	109	102	87
5	Left Front Door	148.0	156	155	133
6	Center Panel Left				
7	Left Rear Door	144.0	149	140	143
8	Left Back Panel	148.6	146	143	157
9	Right Front Fender	94.8	88	97	100
10	Right Front Door	142.0	132	145	149
11	Center Panel Right				
12	Right Rear Door	150.3	154	151	146
13	Right Back Panel	153.3	161	143	156

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	E
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Rear Seat - Worn - Yes / (R) Front Seat - Worn - Yes / Carpet - Worn, Scratch, Cut, Crack - Minimal / (L) Front Seat - Worn - Yes / (L) Front Floor Mat - Worked - Small / Knobs - Worn, Peel, Crack - Small</p>		<p>Remarks Roof - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Small / Roof - Dent - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	C
<p>Remarks Defects not found</p>		<p>Remarks Air Conditioner - Function - Weak / Spare Key - Issue - Unexist</p>	

Inspector Notes
with warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on tail light, air-conditioning system issue