

General Information

Date & Time: 01, Aug, 2025 10:01

Make	Toyota	Model	Wigo
YOM	2022	Odo Meter Reading	58,044
Registration No.	DAR2266	Chassis No.	MHKA4DF5FNJ070901
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Yellow		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	160.6	167	177	138
2	Boot Lid	162.3	150	171	166
3	Roof	146.5	109	162	153/162
4	Left Front Fender	167.0	152	176	173
5	Left Front Door	175.0	172	186	167
6	Center Panel Left				
7	Left Rear Door	179.0	181	179	177
8	Left Back Panel	157.0	161	163	147
9	Right Front Fender	256.0	296	262	210
10	Right Front Door	272.6	273	271	274
11	Center Panel Right				
12	Right Rear Door	272.6	278	254	286
13	Right Back Panel	224.0	208	234	230

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (R) Front Trim - Grime - Medium / Rear Seat - Worn - Yes / (R) Front Seat - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / Ceiling - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes	Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Small / Trunk Hood, Rear Gate - Dent - Minimal / (L) Rear Fender, Molding - Crack, Gap - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Front Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Repair mark - Yes / (R) Rear Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Repair mark - Yes / (L) Rear Door, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Repair mark - Yes / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Repair mark - Difference in Color / Front Bumper, Grille, Lamps - Repair mark - Difference in Color
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/with jack and incomplete tools/No warranty booklet/front and back bumper difference color