

General Information

Date & Time: 28, Jul, 2025 14:51

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	21,357
Registration No.	GAP3893	Chassis No.	PA1B18F34N4194607
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.4	103	102	96
2	Boot Lid	102.0	97	102	107
3	Roof	86.2	89	84	84/88
4	Left Front Fender	88.2	94	84	86
5	Left Front Door	92.3	93	92	93
6	Center Panel Left				
7	Left Rear Door	96.1	98	98	93
8	Left Back Panel	100.8	106	95	102
9	Right Front Fender	90.0	90	89	91
10	Right Front Door	94.9	88	98	98
11	Center Panel Right				
12	Right Rear Door	102.7	109	99	100
13	Right Back Panel	102.5	103	100	105

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (L) Front Floor Mat - Missing - Yes / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Small / (L) Front Trim - Grime - Small</p>	<p>Remarks (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / (R) Front Fender, Molding - Scratch & Dent - Minimal / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Medium / Roof - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>Possible flooding. With warranty booklet and jack. Without spare tire, tools and seat cover. 3 keys. With LTO plate.</p>