

General Information

Date & Time: 16, Nov, 2024 13:36

Make	Toyota	Model	Vios
YOM	2024	Mileage	11,357
Registration No.	NHH6817	Chassis No.	PA1B18F32R4243308
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.6	121	107	110
2	Boot Lid	107.0	103	109	109
3	Roof	104.5	102	111	97/108
4	Left Front Fender	96.3	98	98	93
5	Left Front Door	99.3	100	100	98
6	Center Panel Left				
7	Left Rear Door	98.3	100	98	97
8	Left Back Panel	109.0	116	109	102
9	Right Front Fender	108.3	107	110	108
10	Right Front Door	110.3	109	110	112
11	Center Panel Right				
12	Right Rear Door	113.3	112	114	114
13	Right Back Panel	112.3	109	109	119

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Cut, Crack - Minimal	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

hairline scratches around the exterior. with warranty booklet, user manual and tools. dirt marks at the trunk room.