

General Information

Date & Time: 30, Jul, 2025 09:47

Make	Mercedes-Benz	Model	GLC 200
YOM	2018	Odo Meter Reading	22,250
Registration No.	NCU5846	Chassis No.	WOC2523421F413C44
CC	2.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	79.1	72	69	97
2	Boot Lid	120.0	119	131	110
3	Roof	91.0	75	66	151/72
4	Left Front Fender	73.6	75	78	68
5	Left Front Door	145.0	146	151	138
6	Center Panel Left				
7	Left Rear Door	135.6	135	136	136
8	Left Back Panel	131.6	130	133	132
9	Right Front Fender	74.8	77	68	80
10	Right Front Door	133.3	128	132	140
11	Center Panel Right				
12	Right Rear Door	130.3	128	130	133
13	Right Back Panel	129.6	134	119	136

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	B
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Ceiling - Grime - Minimal</p>		<p>Remarks Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch - Small / (R) Front Wheel, Cover - Scratch, Corrosion - Small / (R) Rear Wheel, Cover - Scratch, Corrosion - Small / (L) Rear Wheel, Cover - Scratch, Corrosion - Small / (L) Front Wheel, Cover - Scratch, Corrosion - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Defects not found</p>	

Inspector Notes
With LTO plate and Sparetire and Incomplete Tools. no Jack and Warranty booklet, scratch headlight and tail light.