

General Information

Date & Time: 30, Jul, 2025 12:07

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	21,131
Registration No.	BAF6917	Chassis No.	PA1B18F35P4234020
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.0	115	102	101
2	Boot Lid	95.5	93	93	101
3	Roof	98.6	100	102	92/101
4	Left Front Fender	92.6	98	84	96
5	Left Front Door	94.3	96	94	93
6	Center Panel Left				
7	Left Rear Door	98.9	103	97	97
8	Left Back Panel	100.0	102	95	103
9	Right Front Fender	96.2	95	97	97
10	Right Front Door	103.2	115	94	101
11	Center Panel Right				
12	Right Rear Door	101.8	97	98	111
13	Right Back Panel	103.2	108	97	105

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes	Remarks (R) Front Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch, Peeled - Minimal / (R) Rear Door, Molding - Scratch - Large / (R) Front Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with lto plate,with jack and tools, with spare tire, with seat cover, 1 key,no warranty booklet,gap at right front fender and right front door