


General Information

Date & Time: 30, Jul, 2025 10:19

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	17,149
Registration No.	CCG3861	Chassis No.	PA1B18F39R4266407
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.3	107	100	100
2	Boot Lid	115.0	109	116	120
3	Roof	96.5	101	95	97/93
4	Left Front Fender	99.0	100	100	98
5	Left Front Door	100.1	96	100	105
6	Center Panel Left				
7	Left Rear Door	110.0	114	105	111
8	Left Back Panel	108.6	118	106	102
9	Right Front Fender	102.0	106	101	99
10	Right Front Door	95.0	91	94	101
11	Center Panel Right				
12	Right Rear Door	97.0	100	92	100
13	Right Back Panel	98.8	100	93	104

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Medium / Roof - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet, with jack and tools, 3keys, with spare tire, with lto plate, no seat cover