

General Information

Date & Time: 05, Aug, 2025 10:32

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	8,134
Registration No.	NJA1109	Chassis No.	PA1B18F34R4274060
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.3	100	114	108
2	Boot Lid	106.4	97	106	116
3	Roof	96.4	104	98	85/99
4	Left Front Fender	97.3	103	91	98
5	Left Front Door	101.3	99	102	103
6	Center Panel Left				
7	Left Rear Door	97.6	102	99	92
8	Left Back Panel	109.3	107	106	115
9	Right Front Fender	98.0	96	95	104
10	Right Front Door	155.6	154	152	161
11	Center Panel Right				
12	Right Rear Door	105.6	102	100	115
13	Right Back Panel	113.0	115	107	117

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Smell - Yes	Remarks (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Minimal / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Roof - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

With warranty booklet and Sparetire, Incomplete Tools and Jack. No LTO plate, Scratch on headlight and tail light.