

General Information

Date & Time: 01, Aug, 2025 12:55

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	14,393
Registration No.	NKJ9340	Chassis No.	PA1B18F38R4266172
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.0	124	101	120
2	Boot Lid	121.0	116	126	121
3	Roof	111.0	113	114	107/110
4	Left Front Fender	111.0	112	109	112
5	Left Front Door	109.3	110	111	107
6	Center Panel Left				
7	Left Rear Door	106.0	108	105	105
8	Left Back Panel	113.6	127	114	100
9	Right Front Fender	117.6	123	114	116
10	Right Front Door	112.6	123	108	107
11	Center Panel Right				
12	Right Rear Door	112.6	104	108	126
13	Right Back Panel	111.6	107	109	119

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Rear Trim - Cut, Crack - Minimal / Rear Seat - Grime - Medium / Ceiling - Grime - Medium / (R) Front Floor Mat - Missing - Yes / (R) Front Seat - Grime - Large / (L) Front Seat - Grime - Medium</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Roof - Dent - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Dent - Medium / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, no warranty booklet, with jack and incomplete tools, with spare tire</p>