

General Information

Date & Time: 05, Aug, 2025 15:24

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	8,149
Registration No.	NHU3141	Chassis No.	PA1B18F32R4270461
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	129.3	127	133	128
2	Boot Lid	125.3	121	125	130
3	Roof	109.6	119	99	106/115
4	Left Front Fender	106.0	102	111	105
5	Left Front Door	107.6	105	106	112
6	Center Panel Left				
7	Left Rear Door	110.6	118	114	100
8	Left Back Panel	124.0	132	127	113
9	Right Front Fender	117.3	114	128	110
10	Right Front Door	108.0	114	105	105
11	Center Panel Right				
12	Right Rear Door	123.6	107	131	133
13	Right Back Panel	116.6	113	114	123

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Minimal / (L) Front Floor Mat - Worked - Small / Dashboard - Traces of Adhesive Tape - Yes / Knobs - Worn, Peel, Crack - Small	Remarks (R) Front Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Lamps (Brake, Tail, Fog) - Issue - Yes

Inspector Notes

no warranty booklet, with jack, incomplete tools, with spare tire, with LTO plate, scratches on tail light, room lamp issue