

General Information

Date & Time: 05, Aug, 2025 10:31

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	3,087
Registration No.	NEZ2409	Chassis No.	PA1B18F32R4270668
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.0	106	107	114
2	Boot Lid	105.6	101	103	113
3	Roof	97.5	101	99	92/99
4	Left Front Fender	102.0	101	103	102
5	Left Front Door	109.6	108	108	113
6	Center Panel Left				
7	Left Rear Door	114.6	123	116	105
8	Left Back Panel	117.0	125	114	112
9	Right Front Fender	106.3	107	110	102
10	Right Front Door	98.9	102	100	95
11	Center Panel Right				
12	Right Rear Door	100.5	95	99	108
13	Right Back Panel	103.3	99	101	110

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Small	Remarks Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Medium / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/with jack and tools/with warranty booklet/No reverse camera