

General Information

Date & Time: 06, Aug, 2025 09:21

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	15,321
Registration No.	DBP8811	Chassis No.	PA1B18F30R4265811
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	133.0	137	133	129
2	Boot Lid	102.7	99	105	104
3	Roof	127.0	131	135	113/129
4	Left Front Fender	99.6	104	93	102
5	Left Front Door	101.3	98	106	100
6	Center Panel Left				
7	Left Rear Door	107.9	121	106	97
8	Left Back Panel	109.0	115	109	103
9	Right Front Fender	106.3	106	101	112
10	Right Front Door	104.3	109	104	100
11	Center Panel Right				
12	Right Rear Door	106.3	104	105	110
13	Right Back Panel	108.6	111	103	112

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Minimal / (R) Front Trim - Grime - Minimal / (R) Front Seat - Grime - Small / (L) Front Seat - Worn - Yes / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Minimal</p>	<p>Remarks (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Large / Member (Bolted) - Dent - Yes / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet, no jack and tools, no spare tire, with LTO plate, scratches on tail, power steering issue due to weak battery, temporary ORCR</p>