

General Information

Date & Time: 31, Jul, 2025 13:31

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	30,181
Registration No.	NHS2159	Chassis No.	PA1B18F33R4256470
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.6	107	104	100
2	Boot Lid	102.7	99	101	108
3	Roof	97.6	107	95	91/98
4	Left Front Fender	92.7	97	90	91
5	Left Front Door	146.6	150	148	142
6	Center Panel Left				
7	Left Rear Door	154.0	168	150	144
8	Left Back Panel	107.0	112	109	100
9	Right Front Fender	86.8	86	82	93
10	Right Front Door	100.1	94	112	95
11	Center Panel Right				
12	Right Rear Door	159.6	153	153	173
13	Right Back Panel	104.8	102	96	116

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Medium / (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / Mat Other - Grime - Medium / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Grime - Small / Console, Switches, Vents - Traces of Adhesive Tape - Yes	Remarks (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Large / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Repair mark - Yes / (R) Front Fender, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Scratch - Small / Roof - Scratch - Small / Bonnet, Headlight - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

center left aircpn vent issue. USB aux cover missing at radio. With warranty booklet,spare tire,jack,tools and seat cover. 3 keys. With LTO plate.