


General Information

Date & Time: 31, Jul, 2025 16:48

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	43,177
Registration No.	BAF3212	Chassis No.	PA1B18F638P4215610
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.6	109	107	101
2	Boot Lid	268.6	252	287	267
3	Roof	95.9	100	91	97/97
4	Left Front Fender	98.3	104	97	95
5	Left Front Door	98.8	96	98	102
6	Center Panel Left				
7	Left Rear Door	102.9	107	104	98
8	Left Back Panel	162.3	162	152	173
9	Right Front Fender	94.9	99	92	94
10	Right Front Door	100.2	104	99	98
11	Center Panel Right				
12	Right Rear Door	102.6	100	101	107
13	Right Back Panel	103.2	104	99	107

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Medium / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Medium / Rear Seat - Grime - Medium / Mat Other - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Small / (L) Front Floor Mat - Grime - Small	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (L) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / (R) Front Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

Scratches on taillight. With warranty booklet, spare tire, jack and tools. Without seat cover. 1 key. With LTO plate.