

General Information

Date & Time: 31, Jul, 2025 17:08

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	29,595
Registration No.	NFC7282	Chassis No.	PA1B18F30P4222602
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.3	110	109	109
2	Boot Lid	101.3	98	101	105
3	Roof	99.5	94	104	95/105
4	Left Front Fender	97.3	105	94	93
5	Left Front Door	102.7	108	99	101
6	Center Panel Left				
7	Left Rear Door	95.6	101	93	94
8	Left Back Panel	176.6	277	127	126
9	Right Front Fender	115.6	113	113	121
10	Right Front Door	118.3	116	118	121
11	Center Panel Right				
12	Right Rear Door	110.6	113	102	117
13	Right Back Panel	109.3	109	101	118

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B		Exterior Evaluation : B	
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / Mat Other - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Grime - Small		Remarks (L) Rear Fender - Repair Traces - Yes / (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium	
Frame Evaluation : A		Functional Evaluation : A	
Remarks Defects not found		Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist	

Inspector Notes

With warranty booklet, spare tire, jack, tools and seat cover. 1 key. With LTO plate.