


General Information

Date & Time: 31, Jul, 2025 17:26

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	16,661
Registration No.	CCG1319	Chassis No.	PA1B18F36R4277963
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.8	103	98	102
2	Boot Lid	105.3	99	107	110
3	Roof	93.7	101	91	86/97
4	Left Front Fender	98.2	106	95	94
5	Left Front Door	102.6	104	100	104
6	Center Panel Left				
7	Left Rear Door	99.0	98	98	101
8	Left Back Panel	109.6	115	107	107
9	Right Front Fender	88.6	89	85	91
10	Right Front Door	94.1	92	94	97
11	Center Panel Right				
12	Right Rear Door	95.5	98	95	94
13	Right Back Panel	104.6	102	103	109

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Medium / Mat Other - Grime - Medium / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Worked - Small	Remarks (L) Rear Door, Molding - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
Scratches at taillight. Without warranty booklet, spare tire and tools. With jack and seat cover. 3 keys. With LTO plate.