Grading Report

General Information

Date & Time: 16, Nov, 2024 15:11

Make	Toyota	**Model**	Hilux
YOM	2024	**Mileage**	22,058
Registration No.	BAF8379	**Chassis No.**	MR0BA8CD1P0243945
CC	2.8	**Transmission**	M/T
Fuel Type	Diesel	**Type of Body**	Pickup
Colour	Brown		

Body / Panel Condition

#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**121.3**	111	129	124
2	Boot Lid	**96.9**	100	91	100
3	Roof	**116.5**	112	101	148/105
4	Left Front Fender	**105.3**	102	106	108
5	Left Front Door	**106.6**	112	105	103
6	Center Panel Left				
7	Left Rear Door	**115.3**	102	102	142
8	Left Back Panel	**109.3**	103	111	114
9	Right Front Fender	**107.3**	103	110	109
10	Right Front Door	**101.4**	107	102	95
11	Center Panel Right				
12	Right Rear Door	**97.4**	91	96	105
13	Right Back Panel	**110.0**	110	110	110

Overall Evaluation : A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Grading Report

Interior Evaluation : A	Exterior Evaluation : C
a : Cut, Fray **d** : Loose, Deformed **k** : Animal Hair **s** : Smell **t** : Cigarette Burns **x** : Defective **y** : Stain	**A** : Scratch **AU** : Scratch & Dent **B** : Modified **C** : Corrosion **G** : Stone chip **P** : Faded **S** : Rust **SC** : Rust & Corrosion **U** : Dent **X** : Defective **Y** : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / (R) Rear Trim - Worked - Small	**Remarks** (R) Side Gate - Scratch & Dent - Large / Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Defects not found

Inspector Notes