


General Information

Date & Time: 01, Aug, 2025 18:13

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	9,103
Registration No.	CCD2949	Chassis No.	PA1B18F31R4251139
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	0.0	0	0	0
2	Boot Lid	0.0	0	0	0
3	Roof	0.0	0	0	0
4	Left Front Fender	0.0	0	0	0
5	Left Front Door	0.0	0	0	0
6	Center Panel Left				
7	Left Rear Door	0.0	0	0	0
8	Left Back Panel	0.0	0	0	0
9	Right Front Fender	0.0	0	0	0
10	Right Front Door	0.0	0	0	0
11	Center Panel Right				
12	Right Rear Door	0.0	0	0	0
13	Right Back Panel	0.0	0	0	0

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / Mat Other - Grime - Small / (L) Front Trim - Grime - Small / Sunvisor, Sunglass Holder - Missing - Yes / Dashboard - Traces of Adhesive Tape - Yes	Remarks Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Door, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
With warranty booklet, spare tire, jack, tools and seat cover. 1 key. With LTO plate.