

General Information

Date & Time: 05, Aug, 2025 15:17

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	5,143
Registration No.	NFF5056	Chassis No.	PA1B18F36P4237718
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	124.0	130	116	126
2	Boot Lid	122.0	123	120	123
3	Roof	116.7	128	112	119/108
4	Left Front Fender	109.0	104	109	114
5	Left Front Door	112.0	115	102	119
6	Center Panel Left				
7	Left Rear Door	120.6	129	114	119
8	Left Back Panel	124.0	143	121	108
9	Right Front Fender	113.3	124	106	110
10	Right Front Door	112.3	104	109	124
11	Center Panel Right				
12	Right Rear Door	114.6	110	111	123
13	Right Back Panel	118.3	114	119	122

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small / Mat Other - Crinkle - Small / (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Small / (L) Front Floor Mat - Grime - Small	Remarks (R) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / (R) Front Wheel, Cover - Scratch, Corrosion - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : D
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes / Power Steering - Issue - Yes / Reverse Camera - N/A - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate, no warranty booklet, with jack and incomplete tools, with spare tire, abs warning light, power steering issue, traction control warning light