

General Information

Date & Time: 01, Aug, 2025 13:48

Make	Toyota	Model	Wigo
YOM	2024	Odo Meter Reading	13,879
Registration No.	CCG3594	Chassis No.	MHKAA1BC3RJ014745
CC	1.0	Transmission	M/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	79.3	79	88	71
2	Boot Lid	165.6	186	155	156
3	Roof	66.4	75	68	59/64
4	Left Front Fender	73.7	70	76	76
5	Left Front Door	79.4	81	74	84
6	Center Panel Left				
7	Left Rear Door	74.9	77	77	71
8	Left Back Panel	60.7	67	58	57
9	Right Front Fender	76.1	78	75	75
10	Right Front Door	82.2	88	78	81
11	Center Panel Right				
12	Right Rear Door	76.0	74	76	78
13	Right Back Panel	60.9	61	57	65

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Seat - Grime - Small	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

With warranty booklet, spare tire, jack and seat cover. Without tools. 2 keys. With LTO plate.