

General Information

Date & Time: 01, Aug, 2025 12:34

Make	Toyota	Model	Avanza
YOM	2024	Odo Meter Reading	9,001
Registration No.	NFS9837	Chassis No.	MHFAABY7R0022668
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.6	97	106	96
2	Boot Lid	95.9	96	105	87
3	Roof	113.7	118	122	105/110
4	Left Front Fender	98.2	94	99	102
5	Left Front Door	118.3	111	121	123
6	Center Panel Left				
7	Left Rear Door	109.3	111	108	109
8	Left Back Panel	106.8	117	95	108
9	Right Front Fender	101.6	109	99	97
10	Right Front Door	109.0	117	109	101
11	Center Panel Right				
12	Right Rear Door	109.3	107	107	114
13	Right Back Panel	102.9	99	94	116

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small	Remarks (L) Rear Door, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

Left side mirror issue gap. With warranty booklet, spare tire, jack and seat cover. Without tools. 2 keys. With LTO plate.