


General Information

Date & Time: 01, Aug, 2025 16:04

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	31,966
Registration No.	NIN2612	Chassis No.	PA1B18F39P4208214
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.8	105	99	102
2	Boot Lid	110.3	109	110	112
3	Roof	92.6	94	95	85/96
4	Left Front Fender	86.2	89	85	85
5	Left Front Door	93.6	94	98	90
6	Center Panel Left				
7	Left Rear Door	95.7	97	95	96
8	Left Back Panel	174.0	175	145	202
9	Right Front Fender	97.5	96	95	102
10	Right Front Door	101.4	98	104	102
11	Center Panel Right				
12	Right Rear Door	100.3	101	100	100
13	Right Back Panel	98.3	94	96	105

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Grime - Medium / Console, Switchs, Vents - Traces of Adhesive Tape - Yes / Glove Box - Worn, Scratch, Cut, Crack - Medium	Remarks (L) Rear Fender - Repair Traces - Yes / (L) Front Door, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / (R) Front Fender, Molding - Scratch - Medium / (R) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Large / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

Grime on glove box. Without warranty booklet. With Spare tire,jack,tools and seat cover. 1 key. With LTO plate.