


General Information

Date & Time: 16, Nov, 2024 12:44

Make	Toyota	Model	Vios
YOM	2024	Mileage	6,012
Registration No.	DBN3569	Chassis No.	PA1B18F35P4232252
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.6	110	105	114
2	Boot Lid	120.0	119	121	120
3	Roof	104.7	108	107	104/100
4	Left Front Fender	107.0	106	112	103
5	Left Front Door	103.6	102	109	100
6	Center Panel Left				
7	Left Rear Door	107.3	110	105	107
8	Left Back Panel	119.3	123	116	119
9	Right Front Fender	106.0	100	106	112
10	Right Front Door	105.3	101	110	105
11	Center Panel Right				
12	Right Rear Door	102.0	101	100	105
13	Right Back Panel	107.6	104	106	113

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
swirlmarks and hairline scratches around the exterior.with manual and warranty booklet.no tools.