


General Information

Date & Time: 01, Aug, 2025 15:19

Make	Toyota	Model	Raize
YOM	2023	Odo Meter Reading	10,308
Registration No.	EAF4642-1	Chassis No.	MHKAB1BA1NJ027807
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Gray		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	122.7	164	105	99
2	Boot Lid	106.3	107	112	100
3	Roof	96.9	111	100	85/92
4	Left Front Fender	106.2	111	113	95
5	Left Front Door	107.7	110	118	95
6	Center Panel Left				
7	Left Rear Door	104.6	103	105	106
8	Left Back Panel	89.5	84	87	97
9	Right Front Fender	106.1	109	111	98
10	Right Front Door	108.3	105	118	102
11	Center Panel Right				
12	Right Rear Door	100.9	100	99	104
13	Right Back Panel	89.3	100	87	81

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Smell - Yes / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / (L) Rear Trim - Cut, Crack - Minimal / (R) Rear Trim - Cut, Crack - Minimal / Ceiling - Crinkle - Small / Glove Box - Worked - Minimal / Steering Wheel - Worn, Peel, Crack - Small / Instrument Panel - Worked - Minimal	Remarks Bonnet - Repair Traces - Yes / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Roof - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Small / Member (Bolted) - Dent - Yes / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large
Frame Evaluation : A	Functional Evaluation : E
Remarks Defects not found	Remarks Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Door Lock - Issue - Yes / Shift Shock - Function - Weak / Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Parking Brake - Function - Weak / Lamps (Brake, Tail, Fog) - Issue - Yes

Inspector Notes
With LTO plate and Sparetire and Jack, Incomplete Tools/ No warranty booklet/ scratch headlight and tail light/ warning lamps on airbag/ head unit not working/ Aircon Not Working/ Abnormal vibration on engine And Abnormal shiftshock on transmission.