

General Information

Date & Time: 04, Aug, 2025 12:35

Make	Toyota	Model	Wigo
YOM	2024	Odo Meter Reading	8,130
Registration No.	DBM4519	Chassis No.	MHKAA1BC5RJ014519
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Orange		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	130.0	135	128	127
2	Boot Lid	90.1	89	94	87
3	Roof	91.6	100	83	97/86
4	Left Front Fender	93.7	87	98	96
5	Left Front Door	113.0	112	111	116
6	Center Panel Left				
7	Left Rear Door	108.3	114	107	104
8	Left Back Panel	98.6	104	93	98
9	Right Front Fender	87.0	92	86	83
10	Right Front Door	102.6	108	100	100
11	Center Panel Right				
12	Right Rear Door	102.2	98	96	113
13	Right Back Panel	90.5	90	86	95

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / (R) Front Seat - Grime - Minimal / (L) Front Seat - Grime - Small	Remarks (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Minimal / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
With LTO plate and warranty booklet and Sparetire and Jack, Incomplete Tools. Scratch headlight and tail light.