

General Information

Date & Time: 16, Nov, 2024 08:10

Make	Toyota	Model	Rush
YOM	2023	Mileage	24,736
Registration No.	NIN1653	Chassis No.	MHKE8FF3PPK053330
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	94.3	100	92	91
2	Boot Lid	91.9	95	86	95
3	Roof	93.9	80	93	110/93
4	Left Front Fender	91.8	91	94	91
5	Left Front Door	94.3	94	89	100
6	Center Panel Left				
7	Left Rear Door	99.7	105	92	102
8	Left Back Panel	90.1	97	88	86
9	Right Front Fender	94.1	100	91	91
10	Right Front Door	98.2	104	97	94
11	Center Panel Right				
12	Right Rear Door	95.3	97	90	99
13	Right Back Panel	96.6	97	91	102

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (L) Rear Trim - Grime - Small / (R) Rear Trim - Grime - Small / (R) Front Trim - Grime - Medium / Overall Interior - Animal Hair - Yes / Overall Interior - Smell - Yes / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Overall Interior - Worn as per age - Yes	Remarks (L) Front Door, Molding - Scratch & Dent - Medium / (R) Mirror - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

wet trunk carpet/ watermarks under the front and rear carpet/