

General Information

Date & Time: 04, Aug, 2025 12:32

Make	Toyota	Model	Vios
YOM	2021	Odo Meter Reading	73,657
Registration No.	CBK3342	Chassis No.	PA1B18F35M4142028
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	95.4	94	91	101
2	Boot Lid	97.8	98	95	101
3	Roof	94.1	100	93	86/97
4	Left Front Fender	88.3	96	89	80
5	Left Front Door	95.7	96	100	91
6	Center Panel Left				
7	Left Rear Door	87.8	92	87	84
8	Left Back Panel	104.3	111	101	101
9	Right Front Fender	98.0	100	95	99
10	Right Front Door	104.3	109	105	99
11	Center Panel Right				
12	Right Rear Door	117.3	118	114	120
13	Right Back Panel	113.3	102	105	133

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : D	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Grime - Medium / Rear Seat - Grime - Large / (L) Front Floor Mat - Cut, Crack - Large / (R) Front Floor Mat - Worked - Large / (R) Front Trim - Worked - Small / (R) Rear Trim - Worked - Large / (L) Front Trim - Grime - Medium / Overall Interior - Smell - Yes	Remarks (R) Front Door - Repair Traces - Yes / Bonnet, Headlight - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Overall Exterior - Faded(Color, Gloss) - Yes / (L) Front Fender, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch & Dent - Medium / (R) Rear Fender, Molding - Repair mark - Yes / (R) Front Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Repair mark - Yes / (R) Rear Fender, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch & Dent - Medium / Member (Bolted) - Dent - Yes / Roof - Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Large
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Radiator Water Pump - Leak - Yes / Reverse Camera - N/A - Yes / Head Light, High Beam - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet/ no tools/ no low beam light/ possible flooding /with jack and spare tire/ with LTO plate/