


General Information

Date & Time: 04, Aug, 2025 15:31

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	4,246
Registration No.	NJF4355	Chassis No.	PA1B18F33S4283029
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.9	99	108	105
2	Boot Lid	105.3	103	102	111
3	Roof	96.6	103	91	95/97
4	Left Front Fender	97.0	101	95	95
5	Left Front Door	96.2	94	95	99
6	Center Panel Left				
7	Left Rear Door	99.6	104	99	96
8	Left Back Panel	104.0	104	102	106
9	Right Front Fender	89.5	88	90	91
10	Right Front Door	97.8	100	94	100
11	Center Panel Right				
12	Right Rear Door	100.5	93	100	109
13	Right Back Panel	105.0	105	100	110

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : A
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Medium / Mat Other - Grime - Medium / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Grime - Medium	Remarks (L) Front Fender, Molding - Scratch & Dent - Minimal / (R) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
Grime on seat covers. With warranty booklet, spare tire, jack, tools, and seat cover. 1 key. With LTO plate.