


General Information

Date & Time: 04, Aug, 2025 17:11

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	13,879
Registration No.	NKK7698	Chassis No.	MHFAA1BY9R0032697
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	96.9	100	91	100
2	Boot Lid	124.0	112	126	134
3	Roof	124.7	128	133	107/131
4	Left Front Fender	100.5	98	98	106
5	Left Front Door	117.6	108	116	129
6	Center Panel Left				
7	Left Rear Door	110.6	118	105	109
8	Left Back Panel	112.6	120	100	118
9	Right Front Fender	98.9	103	101	93
10	Right Front Door	188.6	127	228	211
11	Center Panel Right				
12	Right Rear Door	136.3	131	139	139
13	Right Back Panel	140.6	108	165	149

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Medium / Mat Other - Grime - Medium	Remarks (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

With warranty booklet, spare tire, jack and seat cover. without tools. 1 key. With LTO plate.