

General Information

Date & Time: 04, Aug, 2025 15:48

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	6,888
Registration No.	CCA8811	Chassis No.	PA1B18F39R4259182
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.0	103	102	104
2	Boot Lid	101.3	102	102	100
3	Roof	96.8	108	92	93/95
4	Left Front Fender	93.0	97	92	90
5	Left Front Door	91.2	90	91	93
6	Center Panel Left				
7	Left Rear Door	92.7	96	91	91
8	Left Back Panel	105.0	109	103	103
9	Right Front Fender	96.1	94	90	104
10	Right Front Door	95.2	99	92	95
11	Center Panel Right				
12	Right Rear Door	91.8	86	92	99
13	Right Back Panel	103.1	100	105	105

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small	Remarks (L) Front Door, Molding - Dent - Small / (L) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Dent - Small / (R) Front Door, Molding - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet/with spare tire/with LTO plate/with tools