

General Information

Date & Time: 04, Aug, 2025 14:40

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	23,008
Registration No.	BAG7575	Chassis No.	PA1B18F37R4271105
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.3	116	111	116
2	Boot Lid	115.0	116	114	115
3	Roof	101.7	107	100	97/103
4	Left Front Fender	104.6	101	105	108
5	Left Front Door	104.6	104	103	107
6	Center Panel Left				
7	Left Rear Door	107.0	107	111	103
8	Left Back Panel	124.0	140	111	121
9	Right Front Fender	96.6	97	93	100
10	Right Front Door	100.0	92	103	105
11	Center Panel Right				
12	Right Rear Door	103.5	97	105	109
13	Right Back Panel	112.3	108	107	122

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Medium / Mat Other - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Cut, Crack - Medium / Dashboard - Traces of Adhesive Tape - Yes	Remarks Rear Windshield - Damaged - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
Damaged Rear Windshield. Grime at dashboard. With warranty booklet, spare tire, jack, tools and seat cover. 3 keys. With LTO plate.