

General Information

Date & Time: 16, Nov, 2024 08:00

Make	Toyota	Model	Avanza
YOM	2024	Mileage	9,804
Registration No.	DBN9203	Chassis No.	MHFAA1BY8P0020621
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	147.3	144	148	150
2	Boot Lid	133.0	131	141	127
3	Roof	151.7	165	172	136/134
4	Left Front Fender	135.3	131	127	148
5	Left Front Door	148.6	141	150	155
6	Center Panel Left				
7	Left Rear Door	147.3	150	145	147
8	Left Back Panel	148.0	150	135	159
9	Right Front Fender	134.6	142	131	131
10	Right Front Door	147.6	153	150	140
11	Center Panel Right				
12	Right Rear Door	145.3	153	139	144
13	Right Back Panel	135.3	150	124	132

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with spare tire tools/jack and warranty booklets