

General Information

Date & Time: 04, Aug, 2025 16:21

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	11,314
Registration No.	BAG7804	Chassis No.	PA1B18F35R4269966
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	109	111	110
2	Boot Lid	108.6	108	107	111
3	Roof	100.7	106	97	100/100
4	Left Front Fender	101.3	96	105	103
5	Left Front Door	99.8	101	100	99
6	Center Panel Left				
7	Left Rear Door	102.4	107	103	97
8	Left Back Panel	121.3	127	117	120
9	Right Front Fender	103.6	103	102	106
10	Right Front Door	100.9	101	102	100
11	Center Panel Right				
12	Right Rear Door	104.4	98	106	109
13	Right Back Panel	112.3	106	110	121

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / Mat Other - Grime - Small / (L) Rear Trim - Grime - Small / (L) Front Floor Mat - Grime - Small	Remarks (R) Front Fender, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Medium / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Minimal / Front Windshield - Scratch, Stone chip - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
Scratch on front windshield. With warranty booklet, spare tire, jack, tools and seat cover. 3 keys. With LTO plate.