

General Information

Date & Time: 06, Aug, 2025 14:27

Make	Mitsubishi	Model	Xpander
YOM	2023	Odo Meter Reading	63,892
Registration No.	DAR4012	Chassis No.	MK2LRNC1WPN001960
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Gray		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	79.1	78	85	74
2	Boot Lid	91.9	103	88	85
3	Roof	107.2	122	105	101/101
4	Left Front Fender	93.5	99	95	87
5	Left Front Door	95.0	94	93	99
6	Center Panel Left				
7	Left Rear Door	104.6	110	100	104
8	Left Back Panel	103.6	101	102	108
9	Right Front Fender	138.3	150	119	146
10	Right Front Door	150.6	152	139	161
11	Center Panel Right				
12	Right Rear Door	140.6	136	128	158
13	Right Back Panel	97.3	100	101	92

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Cut, Crack - Small / Ceiling - Grime - Minimal / Dashboard - Worn, Scratch, Cut, Crack - Minimal / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Trim - Grime - Small	Remarks (L) Front Door, Molding - Dent - Small / (R) Rear Fender, Molding - Dent - Small / (R) Rear Door, Molding - Dent - Minimal / Trunk Hood, Rear Gate - Dent - Small / Bonnet, Headlight - Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Audio, Radio - Issue - Yes

Inspector Notes
with LTO plate/with spare tire/with warranty booklet/No jack and tools/with reverse camera/with spare key/audio issue