

General Information

Date & Time: 06, Aug, 2025 12:55

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	36,029
Registration No.	NIU8991	Chassis No.	PA1B18F31R4243476
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	91.0	94	84	95
2	Boot Lid	98.6	91	106	99
3	Roof	93.5	94	92	87/102
4	Left Front Fender	91.2	89	88	97
5	Left Front Door	93.5	92	93	96
6	Center Panel Left				
7	Left Rear Door	100.1	105	98	98
8	Left Back Panel	107.0	115	105	101
9	Right Front Fender	97.3	101	89	102
10	Right Front Door	99.9	96	102	102
11	Center Panel Right				
12	Right Rear Door	97.0	88	102	101
13	Right Back Panel	102.1	103	99	105

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Worked - Large	Remarks Rear Bumper, Lamps, Panels - Repair mark - Difference in Color / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Fender, Molding - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Medium / (L) Front Fender, Molding - Scratch - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Minimal / Bonnet, Headlight - Scratch - Large
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes

Inspector Notes

abnormal noise at the back during idle/ with LTO plate and Jack and tools and warranty booklet/