

General Information

Date & Time: 07, Aug, 2025 10:37

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	17,462
Registration No.	CCK3136	Chassis No.	PA1B18F36R4278692
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.0	111	107	118
2	Boot Lid	105.0	107	106	102
3	Roof	100.7	103	96	99/105
4	Left Front Fender	103.7	107	106	98
5	Left Front Door	102.0	104	102	100
6	Center Panel Left				
7	Left Rear Door	107.0	113	112	96
8	Left Back Panel	114.0	120	113	109
9	Right Front Fender	100.3	99	98	104
10	Right Front Door	101.2	108	97	99
11	Center Panel Right				
12	Right Rear Door	102.9	99	100	110
13	Right Back Panel	102.7	104	99	105

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Trim - Cigarette Burns - Burnt / (L) Rear Trim - Grime - Small / (R) Front Trim - Grime - Small</p>	<p>Remarks (R) Front Fender, Molding - Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Large / Front Bumper, Grille, Lamps - Repair mark - Difference in Color / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Fender, Molding - Crack, Gap - Medium / (R) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet/ incomplete tools/ with jack and spare tire/ with LTO plate</p>