

## General Information

Date & Time: 06, Aug, 2025 17:09

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	40,229
<b>Registration No.</b>	CAZ9852	<b>Chassis No.</b>	PA1B18F31R4239749
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.0	102	102	114
2	Boot Lid	101.0	101	101	101
3	Roof	96.5	93	97	100/97
4	Left Front Fender	93.1	95	92	93
5	Left Front Door	99.0	94	96	107
6	Center Panel Left				
7	Left Rear Door	105.0	105	106	104
8	Left Back Panel	106.3	109	108	102
9	Right Front Fender	99.3	96	98	104
10	Right Front Door	99.7	100	100	100
11	Center Panel Right				
12	Right Rear Door	98.3	99	95	101
13	Right Back Panel	109.3	109	105	114

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Medium / Mat Other - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Missing - Yes</p>	<p><b>Remarks</b> Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Large / Rear Bumper, Lamps, Panels - Repair mark - Yes / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch &amp; Dent - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / Bonnet, Headlight - Scratch - Medium / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Dent - Minimal / (R) Rear Door, Molding - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>Scratches and Crack on taillight. Gap at rear bumper. Without warranty booklet. With Spare tire,jack,tools and seat cover. 1 key. With LTO plate.</p>