

General Information

Date & Time: 07, Aug, 2025 12:19

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	22,789
Registration No.	CCF3924	Chassis No.	PA1B18F33R4263986
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	93.7	97	88	97
2	Boot Lid	100.3	97	103	101
3	Roof	93.3	98	96	92/88
4	Left Front Fender	93.4	95	93	92
5	Left Front Door	87.9	87	90	87
6	Center Panel Left				
7	Left Rear Door	92.1	97	95	84
8	Left Back Panel	101.9	105	102	99
9	Right Front Fender	92.9	97	91	91
10	Right Front Door	92.7	98	94	87
11	Center Panel Right				
12	Right Rear Door	94.1	89	90	103
13	Right Back Panel	96.4	87	94	108

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (L) Front Floor Mat - Cut, Crack - Medium / (R) Front Floor Mat - Grime - Medium	Remarks (L) Front Door, Molding - Dent - Large / Front Bumper, Grille, Lamps - Crack, Gap - Medium / (R) Front Fender, Molding - Dent - Medium / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Front Fender, Molding - Partially Missing - Yes / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet and LTO plate/ with jack and tools/ no spare tire/