

General Information

Date & Time: 18, Nov, 2024 08:45

Make	Toyota	Model	Vios
YOM	2024	Mileage	16,980
Registration No.	DBO2340	Chassis No.	PA1B18F32P4236890
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.3	126	119	125
2	Boot Lid	119.3	117	119	122
3	Roof	115.5	113	120	113/116
4	Left Front Fender	110.6	115	107	110
5	Left Front Door	113.0	118	107	114
6	Center Panel Left				
7	Left Rear Door	115.0	109	121	115
8	Left Back Panel	117.3	122	118	112
9	Right Front Fender	113.6	119	107	115
10	Right Front Door	114.3	120	113	110
11	Center Panel Right				
12	Right Rear Door	125.3	116	127	133
13	Right Back Panel	123.0	125	118	126

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium	Remarks Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Rear Fender, Molding - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Wheel, Cover - Scratch, Corrosion - Small / (L) Rear Wheel, Cover - Scratch, Corrosion - Small / (L) Front Wheel, Cover - Scratch, Corrosion - Small
Frame Evaluation : B	Functional Evaluation : B
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Retractable Mirror - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes

Inspector Notes
no reverse camera feature/ manual mirror controls/ with tools and spare tire and jack/ with warranty booklet